






## API Bottom Loading Adaptor

# 880-405



**880-214  
Handle  
Hub-Assembly**



ITEM	NAME	880-405 REQ'D.	QTY.	PART NO.
	Service Kit		1	90006
	Service Kit includes:			
	(1) Item 1	(1) Item 9		
	(1) Item 4	(1) Item 10		
	(1) Item 8	(1) Item 18		
1	Poppet Seat Gasket (Viton)	1	880-116-01	
2	Stern with Gear	1	880-105-01	
3	Spring	1	880-127-01	
4	Seal Ring (Viton)	1	11034-02	
5	Latch	1	880-212-01	
6	Soc. Hd. Cap Screw	1	11030-09	
7	Spirol Pin	1	11086-04	
8	Socket Hd. Cap Screw (S.S.)	3	11170-07	
9	"O" Ring (Viton)	1	11062-02	
10	"O" Ring (Viton)	2	11039-02	
11	Shaft	1	880-101-01	
12	Grooved Pin	1	11130-01	
13	Gear	1	880-106-01	
14	Socket Hd. Cap Screw	8	11030-06	
15	Handle	1	880-211-01	
16	Locknut	1	11109-01	
17	Grease Fitting	1	11111-01	
18	Flat Hd. Soc. Cap Screw	3	11067-03	
19	Body (Openable) Style	1	880-400-02	
20	API Adaptor	1	880-401-01	
21	Hub	1	880-217-01	
22	Latch Plate	1	880-172-01	
23	Insert	3	880-173-01	
24	Seal Retainer	1	880-126-01	
25	Poppet Spring Guide	1	880-201-01	
26	Retaining Ring	2	11001-03	
27	Hatch Spring	1	880-216-01	
28	Washer	2	880-117-01	
29	Handle Ass'y.	1	880-205-01	